

# **Leisure Unlimited, Inc.**

***Vinyl Liner Replacement Specialists***



***We offer prompt and reliable liner replacement services backed by over 20 years of experience. Please call us at any of the numbers listed below.***

***Leisure Unlimited, Inc.  
216-292-4545  
Terry  
216-990-2781  
Ron  
216-990-3167  
EMail  
LeisureUnlimited@sbcglobal.net***

# Measuring The Pool

Your pool should be measured after it is empty and the old liner is removed. This allows accurate measurements to within 1/2 of an inch on all dimensions. Other potential problems with liner fit can also be easily seen and accommodated for -- before the liner is ordered.




Photos, such as these, are sent to the factory; enabling them to make a better fitting liner.



**Your new liner will look better and last longer. If the pool is properly measured !!!**

We have the expertise and experience that is necessary to measure and fit complex pool shapes that may contain difficult to measure features such as interior steps or multiple level bottoms.



This pool was measured to the 1/4" at 63 perimeter points, 6 cross and diagonal measurements, and at least a dozen more bottom points depicted in a second blue print.



# The Pool Bottom

It is difficult to determine the exact condition of a pool bottom until the liner is removed. Pool bottoms can deteriorate from leaks in the liner, ground water problems, or poor materials and workmanship when the pool was installed.

## Hard Bottoms

Before



This bottom has ground water damage but is fully repairable. All loose pieces and soft areas will be removed and a cement/vermiculite pool bottom mix will be troweled into place.

After



This pool's bottom was extremely thin in some areas, and required spot patching with sand and cement.

# The Pool Bottom.....continued

## Sand Bottoms



This sand bottom was carefully cleaned by hand, and then trowled smooth just before the liner was fitted.



This pool's bottom was reshaped, and a new hard bottom installed.



# Pool Wall Foam


- \* Protects your new liner from rusting steel wall panels or deteriorating wood wall panels.
- \* Creates a smooth even surface for the new liner.
- \* Insulates your pool wall.



**We use pool wall foam that does NOT absorb water, and glue it into place with waterproof adhesive.**

# Special Situations

This damaged coping will not securely hold the liner in place. Liner "Bead Lock" is used to hold the liner bead in place.



Arrow points to installed section of Bead Lock.



This rusted section is repaired with a galvanized steel patch and covered with wall foam.

## Special Situations.....continued



Older pools often have corners that will no longer hold the liner.



A new piece of aluminum corner tracking is installed with stainless steel fasteners.

The new track is almost invisible, and the liner is now secure.



**Leisure Unlimited's expertise and fine craftsmanship results in a longer lasting and better looking liner replacement.**





**Proper Liner Sizing...**

**Meticulous Preparation...**

**Attention To Detail...**

***Leisure Unlimited's Formula  
For Longer Lasting  
&  
Beautiful Liner Installations***